## **Comments for VOC QAPP from MarkWest**

Submitted by R3 Air Quality Analysis Branch (AQAB) 07/25/2019

Element	Element No.	Page	Comment
EPA Region 3 Quality Assurance Coordinators	A.4.4	A-9	Revise first sentence to, "EPA Region 3 Quality Assurance Coordinators, Kia Long and Verena Joerger, will direct [serve as points of contact for] all-quality assurance activities as related to the air toxics and meteorological monitoring program at the Harmon Creek Gas Processing Plant".
EPA Region 3 Monitoring Technical Lead	A.4.5	A-9	Revise to say, "Lori Hyden will serve as the VOC monitoring point of contact for EPA Region 3". Lori Hyden is Loretta Hyden (email [ HYPERLINK "mailto:hyden.loretta@epa.gov" ]).
Organizational Chart	Figure A.1	A-13	Revise the organizational chart so that it includes one box labeled, "EPA Region 3" with a dotted communication line to Nick Lazor (include on same level).
Level 0 Data Validation	D.1.2	D-2	"MSI Trinity's QC software is validated in accordance with MSI Trinity's SOP 117 which is presented in Appendix C". SOP 117 is not included in Appendix C of this QAPP. Please add this SOP or describe software validation procedures.
Level 1 Data Validation	D.1.4	D-7	"For the air toxics, pollutant data between 0 and -10ppb are set to 0". The CD requires that the air toxics data be treated in accordance with the NATTS TAD. The NATTS TAD does not allow for zero substitution (see NATTS TAD section 3.3.1.3.15).

[ PAGE \\* MERGEFORMAT ]